

# Noise

## Mitigation Monitoring Report




October 2007

**Most Compliant  
Airline:**


**United**

Learn about noise mitigation procedures over Tempe on p.7

**Departure Compliance**



Tempe Corridor: **51.7%** with the 4-DME SID




Phoenix Gate: **97.2%** with the 4-DME SID



Tempe Aviation Commission

This report is assembled for the Tempe Aviation Commission (TAVCO) to monitor the monthly compliance of operations at Phoenix Sky Harbor International Airport with certain noise mitigation flight procedures over the City of Tempe. TAVCO consists of 13 Tempe residents appointed by the Tempe Mayor with approval of the City Council to assist and advice on aviation noise and other issues relating to the Phoenix Sky Harbor International Airport, which is owned and operated by the City of Phoenix. The City of Tempe is located directly east of the airport's 3 parallel runways.


**Aircraft Noise Energy Levels:**



LdnA or day-night level (DNL), is a descriptor of noise level based on energy equivalent noise level (Leq) over the whole day with a penalty of 10 dB(A) for night time noise (22.00-7.00 hrs). DNL is used to forecast noise exposure contour lines around airports.




**PHX Noise Monitors in Tempe:**

Noise Monitor Sites and PHX FAR Part 150 1999 65 –70 DNL contour lines in Tempe.





**Peak Noise Levels:**

Lmax is the maximum sound level (dB) registered during a particular noise event. One aircraft departure, arrival or overflight typically results in noise events being registered at more than one NMS. The depicted maximum noise levels were registered at NMS 9 & 11 (Cook College and Theological School & Tempe Beach Park).




AAY | Allegiant Air | CCI | Capital Cargo International | MEP | Midwest Express  
 See other airline codes below on p. 5.

**East Operations Summary:**





**Corridor Compliance with 4-DME Standard Instrument Departure procedure:**




4-DME deviations during the following hours has been identified by PHX as being weather impacted, and has not been included:

- 10/1 12:48 - 12:55
- 10/4 09:09
- 10/4 11:44
- 10/5 04:26 - 11:08
- 10/8 09:46 - 12:06
- 10/8 19:07 - 21:08
- 10/13 05:34
- 10/15 07:58 - 08:12
- 10/16 09:59
- 10/16 11:00 - 11:27
- 10/21 08:20 - 23:56
- 10/22 06:05 - 12:45
- 10/22 13:34
- 10/22 17:10 - 17:11
- 10/23 08:08 - 10:09
- 10/24 01:49
- 10/24 16:25 - 16:50
- 10/24 19:44 - 19:55
- 10/25 09:07 - 10:27
- 10/25 14:29
- 10/27 10:17 - 10:52
- 10/28 16:46 - 16:54
- 10/29 12:41
- 10/29 1354-1448
- 10/30 1137 - 1149






**Notices of Deviation:**





Includes the following airlines with more than 10 departures to the east:

AMF	Ameriflight	SWQ	Swift Air	ABX	Airborne Express	AMX	Aero Mexico	ASA	Alaska Airlines	ASH	Mesa Airlines	NWA	Northwest Airlines
FDX	Federal Express	UPS	UPS	OPT	Flight Options	SWA	Southwest Airlines	BTA	Continental Express	AWE	America West	USA	US Airways
EJA	Executive Jet Aviation	FIV	Citation Chares	SKW	Sky West	AAL	American Airlines	COA	Continental Airlines	DAL	Delta Airlines	UAL	United Airlines

**East/West Departure Split:**




**Received Complaints:**



Incursions = Over flights identified to individual aircraft.

4 Tempe residents made complaints to the City of Tempe in September 2007 reporting:

- Low flying helicopters over south Tempe and Chandler.
- Noisy airlines on a descending path just south of Elliot Road.
- Late evening arrivals and early morning departures during the week end disturbing sleep.
- Incoming Southwest flight from Las Vegas, executing a go around climbing out towards the southeast over central Tempe.
- US Airways/America West departure bound for San Diego turned away from the riverbed after take off. The maneuver was not initiated by directions from PHX ATC.



PHX carrier departures = —  
 PHX carrier arrivals = —  
 PHX over flights = —

A citizen's notes on disturbing helicopter activity in the border areas of Tempe and Chandler east of I-10 for the months of February to October 2007 are included in the complaint numbers.

### IGA on Noise Mitigation Flight Procedures:

In 1994 the City of Phoenix and the City of Tempe agreed to continue noise mitigation flight procedures already in use over Tempe from the Phoenix Sky Harbor International Airport. The IGA was made after City of Tempe had challenged the plans for the construction of a third runway because of inadequate assessment of the environmental impacts, and the legal challenge was mediated and settled. The City of Phoenix agreed to submit a F.A.R. Part 150 Noise Compatibility study for the Phoenix Sky Harbor International Airport where the following agreed upon measures were included:


1. Have jet and large turboprop aircraft depart to the east over the Salt River.
2. On an annual basis equalize the noise burden from jet and large turboprop aircraft departures between east and west during daytime and nighttime hours.



3. The agreement also included a new procedure for mitigation noise from arriving jets and large turboprop aircraft to the proposed third runway (25L).



According to the 1993 Environmental Impact Statement for Phoenix Sky Harbor International Airport master plan improvements that included construction of the third runway, the 1-DME Standard Instrument Departure Procedure was to be continued for noise mitigation purposes. After the VORTAC was moved, it became the 4-DME SID.




The Tempe Aviation Commission used the SID to come up with a "Corridor" to measure airline compliance with the 4-DME SID. The airport uses a 5,500 feet long imaginary line, "Gate", running north south at 4-DME or approximately at Price Road. Turns by carrier jets north or south away from the Salt riverbed before reaching this line results in a notice of deviation from the airport to the responsible airline.



On March 27, 2002 the FAA suspended formalization of a "side step" procedure that had been in use after the third runway opened in October 2000. Presently the FAA is clearing jets and large turboprop aircraft for straight-in approaches to Runway 25L from the east. 4 contributing factors led to negative effects on flight safety and the decision to suspend the side step procedure:

1. The destabilizing effect on the approach.
2. The inability to intercept the glide slope for the third runway.



Because the threshold for Runway 25L is located farther west than the threshold for Runway 25R, the glide slope is higher up than the glide slope to Runway 25R. Using the Runway 25R glide slope a pilot would need to apply power and both turn and climb close to landing to intercept the glide slope for Runway 25L when executing the side step maneuver when abeam Sun Devil Stadium.

3. Computer reprogramming going on in the cockpit.
4. Loss of visual reference, particularly at night (Sun Devil Stadium not always being lit).